

Zlin Aviation s.r.o.

2. Května 685
763 61 Napajedla

CAUTION

Savage maintenance

- **Airplanes affected**
Savage, all Models and Serial numbers
- **Reason**
Addition to the maintenance manual.
- **Subject**
Visually check all stainless steel tail plates (16 pieces) for the fixation of the cable on the horizontal stabilizer.
- **Compliance**
Date of Issue of technical advice.
- **Accomplishment**
Every year during annually check or every 50 hours of operation, whichever occurs first, you must make a visually check of all steel tail plates (16).
Visually check for cracks in the area of the holes and in the bending zone.
Too little tension in the steel wiring for the horizontal stabilizer creates little vibrations that could harm the steel plates. Make sure the cable have the right tension. If in doubt, call your dealer for further assistance.
Note this check in your maintenance manual. If you are not able to check and comply personally, ask us or a technician for further assistance.
If there are not anomalies found regarding those parts the plane is airworthy.
It is only an addiction to the maintenance manual, there is no Savage model affected by this problem



12 pieces

4 pieces